

## NMC Global Corporation

650 Grove Road, Suite 111, P.O. BOX 309, Thorofare, NJ 08086 Tel: 856-686-4904 Fax: 856-686-4907 e-mail: <a href="mailto:nmcglobal@natmar.com">nmcglobal@natmar.com</a> Web site: www.natmar.com

Ref: Sampling and lab analysis on # 6 Fuel Oil from Shore Tank # 15 after discharge of the Barge B-105 at Sprague Rensselaer, NY on April 16, 2005.

File Number: 40462

Sample Number: 40462-15

Ref#: V-05-00667

## CERTIFICATE OF ANALYSIS SHORE TANK # 15

TEST	METHOD	UNITS	RESULT
API Gravity	D-287	° API @ 60 °F	12.4
Viscosity	D-445	cSt @ 122 ° F	388.8
·		SFS @ 122 F	183.5
Sulfur	D-4294	Weight %	1.37
Pour Point	D-97	° F	37
Flash Point	D-93	$^{\circ}\mathrm{F}$	196
Water by Distillation	D-95	Volume %	0.20
Ash	D482	Weight %	0.039
Vanadium	D-5863	PPM	67
Sodium	D-5863	PPM	18
Nitrogen	D-5762	Weight %	0.34
Asphaltenes	IP-143	Weight %	5.8
Heating Value	D-240	BTU / Gal	151,646

SPRAGUE PROVIDES THE ATTACHED INSPECTION REPORT/ANALYSIS
REPRESENTING THE SPECIFICATIONS OF THE PRODUCT AT THE SPRAGUE
TERMINAL IN TANK ON THE DATE OF INSPECTION NOTED ON THE CERTIFICATE.
THIS ANALYSIS IS PROVIDED TO THE CUSTOMER FOR THE PURPOSE OF
ESTABLISHING THE INDEPENDENTLY VERIFIED PRODUCT SPECIFICATION OF THE COMPOSITE BASIS IN SPRAGUE'S TERMINAL SHORE TANK AS NOTED ON THE
CERTIFICATE. THE INSPECTION REPORT IS NOT TO BE USED FOR ANY OTHER
PURPOSE. SPRAGUE DISCLAIMS ANY LIABILITY FOR THE PRODUCT AFTER DELIVERY
BY SPRAGUE TO CUSTOMER. SPRAGUE DISCLAIMS ANY WARRANTY OF
MERCHANTABILITY OR FITNESS FOR AN INTENDED USE EXCEPT AS MAY BE SPECIFICALLY
SET FORTH IN WRITING IN ANY CONTRACT OR TERMS OF SALE BETWEEN SPRAGUE
AND A BUYER OF PRODUCT. SPRAGUE ASSUMES NO LIABILITY FOR CLAIMS OR LOSSES
THAT MAY ARISE FROM CUSTOMERS USE OF THIS INSPECTION REPORT/ANALYSIS.